

CANDIA POLICE DEPARTMENT FACILITY DEFICIENCIES

BOOKING, DETENTION & INTERROGATION

CANDIA POLICE DEPARTMENT



MODERN EXAMPLE



No holding cells and offender confined to room by common wooden door
 No sight/sound separation if multiple prisoners, interviews are done in the cruiser
 AC must stay on all year long, intoxilyzer is temperature and airflow sensitive

LOCKER ROOMS

CANDIA POLICE DEPARTMENT



MODERN EXAMPLE



No privacy for female officers - who must use the only restroom on 2nd floor
 Overflow storage: evidence, large equipment and cruiser snow tire storage
 Door connects to Town Hall

EVIDENCE STORAGE

CANDIA POLICE DEPARTMENT



MODERN EXAMPLE



Inadequate storage solution
 Inadequate evidence processing room
 No ventilation

PUBLIC LOBBY

CANDIA POLICE DEPARTMENT



MODERN EXAMPLE



Shared public reception and prisoner entry
 Confined public waiting area
 Lack of separation and safety

SALLY PORT

CANDIA POLICE DEPARTMENT



MODERN EXAMPLE



Current facility does not have a sally port and vehicles stay outside year-round
 Prisoners enter the facility through shared public entrance
 Safety and security risk during detainee transfer

PATROL ROOM / DUTY OFFICE

CANDIA POLICE DEPARTMENT



MODERN EXAMPLE



6 Officers use one computer for typing reports
 Sloped ceiling, limits usable space, potentially dangerous
 Gun cleaning happens at lunch table